	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Err ors
1	BRS	L1	606	340/310.01.ccls.	USPAT	2002/03/11 07:45			0
2	BRS	L2	335	340/310.02.ccls.	USPAT	2002/03/11 07:45			0
3	BRS	L3	201	340/310.06.ccls.	USPAT	2002/03/11 07:46			0
4	BRS	L4	3463	detection adj mode or measurement adj mode	USPAT	2002/03/11 07:47			0
5	BRS	L5	2863	negative adj resistance	USPAT	2002/03/11 07:48			0
6	BRS	L6	1110	interrogat\$3 near3 sensor	USPAT	2002/03/11 07:48			0
7	BRS	L7	21357	speed adj sens\$3	USPAT	2002/03/11 07:49			0
8	BRS	L8	950	1 or 2 or 3	USPAT	2002/03/11 07:49	2		0
9	BRS	L9	5	4 and 8	USPAT	2002/03/11 07:51			0
10	BRS	L10	1	5 and 8	USPAT	2002/03/11 07:51			0
11	BRS	L11	11	6 and 8	USPAT	2002/03/11 08:02			0
12	BRS	L12	3	7 and 8	USPAT	2002/03/11 08:05			0
13	BRS	L13	15381	modulat\$3 with supply	USPAT	2002/03/11 08:06			0
14	BRS	L14	90	8 and 13	USPAT.	2002/03/11 08:17			0
15	BRS	L15	321	program\$4 adj sensor	USPAT	2002/03/11 08:18			0
16	BRS	L16	1	13 and 15 ·	USPAT	2002/03/11 08:19			0
17	BRS	L17	22655	7 aand 13 and 15	USPAT	2002/03/11 08:19			0
18	BRS	L18	0	7 and 13 and 15	USPAT	2002/03/11 08:20			0
19	BRS	L19	108975 8	built near\$3 sensor	USPAT	2002/03/11 08:21			0
20	BRS	L20	8824	13 and 19	USPAT	2002/03/11 08:21			0
21	BRS	L21	2217	built near3 sensor	USPAT	2002/03/11 08:22			0
22	BRS	L22	23	13 and 21	USPAT	2002/03/11 08:29			0
23	BRS	L23	0	7 and 13 and 21	USPAT	2002/03/11 08:30			0
24	BRS	L24	556	7 and 13	USPAT	2002/03/11 08:31			0
25	BRS	L25	0	5 and 24	USPAT	2002/03/11 08:31			0
26	BRS	L27	0	21 and 26	USPAT	2002/03/11 08:32			0
27	BRS	L26	100	5 and 13	USPAT	2002/03/11 08:33			0
28	BRS	L28	316077	sensor	USPAT	2002/03/11 08:33			0
29	BRS	L29	27	26 and 28	USPAT	2002/03/11 08:33			0